

Potential improvements for traffic calming, accessibility and overall quality of public space.




Challenges Section 1: Cann Hall




Characterised by series of chicanes and defective speed cushions with a long continuous bend in road creating poor visibility especially for east west journeys. No speed signage throughout section. Attractive roadside verge and sightlines across Wanstead flats poorly utilised with limited engagement or provision for active accessibility.

Section 2: Montague & Woodhouse



Characterised by a long straight carriageway, with no speed signage throughout section and very poor surfacing. Poor visual sense of public space dominated by local garages blocking footpaths and carriageways, impeding and endangering safe access for all users. Irregular road widths, parking and traffic calming create hazardous pinch-points along entire stretch.



Characterised by a stretch of single lane carriageway and motor vehicle dominated start/termination point with poor pedestrian accessibility at Harrow Green.

through traffic.

